

U.S. Officials Only

CONFIDENTIAL

Approved For Release 2003/10/01 : CIA-RDP80-00809A000500510046-2

CENTRAL INTELLIGENCE AGENCY

# INFORMATION REPORT

COUNTRY

SUBJECT

PLACE ACQUIRED  
(BY SOURCE)

DATE ACQUIRED  
(BY SOURCE)

DATE (OF INFO.)

Port Information on Tandoe

REPORT NO.

25X1A

RESPONSIVE TO	
1	2
25X1A	

DATE DISTR. 7 JUNE 1954

NO. OF PAGES 2

NO. OF ENCLS.

SUPP. TO  
REPORT NO.

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES, WITHIN THE MEANING OF TITLE 18, SECTIONS 793 AND 794, OF THE U.S. CODE, AS AMENDED. ITS TRANSMISSION OR REVELATION OF ITS CONTENTS TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW. THE DISSEMINATION OF THIS REPORT IS PROHIBITED.

25X1X  
THIS IS UNEVALUATED INFORMATION

SOURCE

[The Office of Naval Intelligence furnished the following information to CIA for IAC dissemination in accordance with paragraph 3c of NSR 110-77. This information was obtained by DIO-3.D and was forwarded as ONI 59-547]

- General:** Tandoe (Lat 14° 03.1' N; Long 123° 10' E) lies at the head of Putauca Bay about two and three-quarters miles southeast of Separation Point. Separation Point is low and wooded at the extremity, but it rises to 3.2 feet about two miles inland. The point is surrounded by a wide beach which is partly dry at low water. The western arm of Putauca Bay extends two miles southeastward. The shores of this arm are fringed with coral reefs, leaving a deep point or over a mile in length by one-half mile wide between them.
- Operations:** Tandoe is the site of a large sawmill owned by Woodward, Inc. Export lumber is loaded aboard ship at the average rate of approximately 90,000 board feet per day of 24 hours per hatch. Local labor is used for stevedoring.
- Entrance:** The approach is not easy and should not be attempted at night, for the reefs on either arm of the bay are not marked. The pier is visible on entering the bay, and care should be exercised when steering for the pier in order to avoid a rock having a least known depth of 10 feet. This rock is situated 1170 yards 134° from the offshore end of the pier.
- Pilotage:** Pilotage is not compulsory but is recommended for large vessels, especially when entering the port the first time. A pilot is available at Mercedes or by special agreement.
- Mooring:** There are no mooring boats to run lines ashore, and vessels must come within the liner's reach to get them ashore. During the northeast monsoon, a port landing is safer. The anchor should be dropped when a reasonable distance from the dock. Once the line is on the dock, the ship should be swung around and beached in. If a starboard landing is mandatory, extreme caution must be shown as the northeast wind, sea, and swell will carry the stern away from the

U.S. Officials Only

CONFIDENTIAL

SEE LAST PAGE FOR SUBJECT & AREA CODES

DISTRIBUTION	STATE	ARMY	NAVY	AIR	FBI

ONI DECLASSIFICATION INSTRUCTIONS ON FILE  
This document contains information which, if disclosed, could be injurious to the national defense. It is to be controlled, stored, handled, transmitted, and disposed of in accordance with the instructions of the Department of Defense and the Central Intelligence Agency. It is not to be transmitted overseas without the concurrence of the originating office through the Assistant Director of the Office of Collection and Dissemination, CIA.

25X1A

- 2 -

CONFIDENTIAL/US OFFICIALS ONLY

dock. If the ship's draft necessitates her after part being exposed to the northeast swell, the vessel will surge and roll badly. Fortunately, the mooring clusters have considerable give, otherwise it would be very hazardous to remain at the dock. Masters should make frequent barometer readings, and when sea and swell build up they should be in a position to cast off before it is too late.

6. Current: - The current ebbs to the west and floods to the east.
7. Pier: - A wooden pier is maintained by Woodworks, Inc. It lies in a direction of approximately 045°-225° and is 420 feet long by 25 feet wide. It has a mean depth alongside of 27 feet, and is in excellent condition. There are 10 fendermooring clusters on the eastern side of the pier, where ocean-going vessels berth.
8. Railroad: A railroad runs from the sawmill to the end of the pier.
9. Crane: A travelling crane of 15-ton capacity is available if required.
10. Supplies: Neither fresh water nor stores are available, but the company maintains a canteen where personal stores may be obtained. Damage is available.
11. Repairs: Minor repairs can be made at a well-equipped machine shop at the mill.
12. Communications: Public postal or telegraphic facilities are not available, the nearest facilities being at Kaga. However, a private post and telegraphic office is maintained by the company.
13. Medical: The mill maintains a company hospital which can furnish medical treatment and perform minor surgery.
14. New Construction: Plans are to construct a new dock in a more northerly direction, enabling vessels to stem the wind, sea, and swell.

- End -

## LIBRARY SUBJECT &amp; AREA CODES

756.548	S
756.545	S
756.543	S
729.43	S

CONFIDENTIAL/US OFFICIALS ONLY

